

Service Bulletin

March 24, 1955
No. 41

REPLACEMENT OF METER COVERS

We have corrected the problem of breakage of meter covers on the Berlant Broadcast and Concertone 20/20 Recorders. Breakage occurred due to excess strain in mounting.

Current production models have cork washers between nut and back of panel. Four nuts are then turned up finger tight.

If you require replacement covers, please specify the following:

1. Make of Meter. This can be determined by examining the dial face. If the words MARION ELEC. INST. CO. are written in the lower left hand corner, please specify MARION. If there is no writing on the dial face, specify BEEDE.

2. Recorder for Which Meter Cover is Desired.
Concertone 20/20 or Berlant Broadcast Recorder.

BERLANT-CONCERTONE

Sid Weiss

Sid Weiss
Service Administrator

SW:bh